## New Bedford Water Works. No. 1.782

RETURN OF SERVICE PIPE.  Westato No. 64 Wreliase Street, for			
Estato No. 64 Oureliase Street, for			
Put in by	Nug	10	7.
Service Pipe 98 inches diameter. June 84 1874			
Cost to be paid by the City.	Cost to be paid by the Proprietor.		./
2 lineal feet earth exc. at ets.	3.5 lineal feet earth excavated at 23cts.		81
lineal feet rock exc. at cts.	lineal feet rock excavated at cts.  5.5 lineal feet lead pipe at 40 cts.	2	20
Lineal feet lead pipe at ets.	Lentuny fremises	2	00
	Amount charged Proprietor,	5	01
Amount paid by the city,	Total Cost,	•	

Uno B Wheeler Superintendent.

SERVICE PIPE, No. 15/82

Laid for bluman

64 Jurchuse Street.

Expense to the City,

Expense to the Proprietor,

Total, - - -

Water Registrar's Office.

New Bedford, 5/29 1874

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate

named on the back of this Order and return the expense thereof, &c., to my

Office. Hallaway
for water Registrar.