New Bedford Water Works. No. 1.886

RETURN	OF SERVICE PIPE.	
Estate No liver	Vemplon 3	treet, for
Put in by	Cely	
Sur in of Lug 29 7 187 Lervice Pipe 3/8 inches diameter. Clug 29 7 187		
Cost to be paid by the City.	Cost to be paid by the Proprietor.	
2 lineal feet earth exc. at cts	H. 5 lineal feet earth excavated at 23 cts.	1 04
lineal feet rock exc. at cts.	lineal feet rock excavated at cts.	2 00
lineal feet iron pipe at cts.	Entury frames	200
Amount paid by the city,	Amount charged Proprietor, Total Cost,	5 04

Geo B Mules superintendent.

A Sh Street PIPE, No. 1886 Laid for Klupton street. August 29" 1874 Expense to the City, Expense to the Proprietor, Zotal,

Water Registrar's Office.

New Bedford, 187 4

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my

Office.

Water Registrar.