## New Bedford Water Works. No. 1978

RETURN	OF SERVICE PIPE.	
Estate No. Goulempland 4th between Janushy & South Street, for		
Put in by  Service Pipe 38 inches diameter.  Coly  Service Pipe 38 inches diameter.		
Service Pipe 18 inches diameter. 1874		
Cost to be paid by the City.	Cost to be paid by the Proprietor.	
14 lineal feet earth exc. at cts.	12 lineal feet earth excavated at 23 cts.	2 76
lineal feet rock exc. at ets.	lineal feet rock excavated at cts.	
13.3 lineal feet lead pipe at cts.	13 lineal feet lead pipe at 40 cts.	5 20
lineal feet iron pipe at cts.	lineal feet iron pipe at cts.	
	Centry prumis	2 00
	Amount charged Proprietor,	9-91
Amount paid by the city,	Total Cost,	/ / 6

Gw 73 Meeles superintendent.

SERVICE PIPE, No. 1978

Laid for John bandle

191 purguista between

Rockland & South street.

187

Expense to the City,

Expense to the Proprietor,

Total, - - - -

Water Registrar's Office.

New Bedford, 24 187

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my

Office. A Mallama

Water Registrar.