

Oct. 28,,1957 - extended 26 ft. from meter box to  
Meter inside bldg. - meter relocated. - Owner's plumber  
Oct. 3, 1947 Inspected by J. Barboza

#22483 Francisco A. Souza  
W.S. Maywood St., S x Brooklawn  
Avenue.

Please install 3/4" City Meter & 3/4"  
Copper Service to supply lot. Box on  
taker's land. Trench dug by taker.

21-20 Trench dug by taker 5'-3/4 deep.	Labor .75
S x S Line Brooklawn Ave.	327.1
EXW " Maywood St.	5.5

No cuts

Laid Oct. 16. 1947

