

1270

Sept. 13, 1951

#23608

Sigmund Glaser  
E. S. Church St., N x Lynn St.

Please install  $3/4"$  Dity Meter &  
 $3/4"$  Copper service to supply bungalow.  
 Trench is ready. South house.

41-40--Trench dug by taker-19' of  $\frac{1}{4}$  Cop \$9.12-Lab \$.75


N x N Line Lynn St. 272.0

W x E " Church St. 9.7

N x S " House 19.0

1 Street cut:  $2\frac{1}{2}'$  x 20' Tarred stone

Work done Sept. 14, 1951



Service Repaired

23608

September 15, 1960

726 Church Street

Installed 2nd. curb stop: W x E line Church St. 5.7  
N x S " House 14.3  
W x W line Front Stop 14.9

1-3/4" copper stop

1 C. I. stop box standpipe and bottom

The old stop is 4 ft. W x The new stop

Stock supplied and installed by Contractor,  
Campanella and Cardì

Work done while widening Church St.

