

194 Riverside Ave

May 23, 1968

#27704

New Bedford Rayon

E. S. Riverside Ave.

S. x Junction Belleville Ave.

Please install 10" C.L.C.I. Taker's service
to supply Plant. 2-6" meters from Ser. #21376
to be transferred to new service #27704 8"
meter to be retained on Ser. 21376

MEASURE OF 10" TAPPING GATE

S X N LINE NASH RD. 27.1

W X E LINE RIVERSIDE AVE. 33.3

THE MAIN IS E X W LINE 18 FT.

WORK DONE MAY 28, 29, 1968

This service laid to meter pit in side walk

21.4 ft. of 10" C.I.C.L. Pipe	\$
1-10" Pc. C.I. 15.7 ft. long " S. C.L.	\$
1-10" Pc. C.I. 27" long " S. C.L.	\$
1- Pc. 10" C.I. 42 " long B.S. C.L.	\$
1-10" X 10" X 10" Tapping sleeve A. P. S.	\$
1-10" Tapping gate. A. P. S.	\$
2-10" 1/8 Bend. B. B. Reg.	\$
5-10" mineral lead joints and gaskets.	\$
8-54 Tapping machine use	\$
Ingersoll Rand Comp. 2 hrs.	\$
Oliver Loader 4 hrs.	\$
1-8" Gate box. Complete Reg. Pattern . . .	\$
Street out 21' X 3' Warrenite W. S.	
Side walk out 8' X 8' Cement E. S.	

JOINT LEAK: 1/8 Bend - Rep. Jan 29, 1971
 Repaired with joint material.