

Tel. 3-1505

2-5838

#27926

#319

264 Bonney St.

March 27, 1969

Robert R. Sylvia

W.S. Cornell St.

N. x Gifford's Lane

Please install 1" copper service to supply ranch house. Main to be extended. Meter - in Box on taker's land. PLEASE CALL DAY BEFORE GOING.

Measures of 1" Curb Stop:

N x N	line	Templeton Street	226.0
E x W	"	Cornell Street	6.0
S x S	"	House	33.0
E x E	"	Meter Box	8.0

Main is 14 ft. E x W line

Work done May 23, 1969

(over)

Service Repaired  
Sept. 28 1972

53' of 1" copper by owner: 14' out. 39' ins.

Labor. . . . .	\$ 14.98
1 1" Hays Corporation. . . . .	5.50
1 1" Hays Curb Stop. . . . .	9.00
1 Buffalo Stop Box, Complete . . . . .	10.00
Carting. . . . .	5.00
Wheeler B-100 tapping. . . . .	14.00
2 1" meter couplings @ 2.25 ea. . . . .	4.50
Loader use: 1 hrs. @ 7.00 hr. . . . .	7.00
1 street cut: 7' x 3' Dirt	
1 sidewalk cut: 10' x 3' Dirt	

---

Service removed from the line cap and \$ 69.98  
 tapped in a straight line into the extended  
 pipe installation; 7 ft. of 1" copper  
 1 male adapter - 1" See Service Repair Report