## New Bedford Water Works. No.481

RETURN OF SERVICE PIPE.

ESTATE No. 86		
Willia	un A. Dana	
Put in by Hifford V	Allen Contractors	
Service Pipe 3/4 inches diameter.	Oct- 10th 1870	

Cost to be paid by the City.			Cost to be paid by the Proprietor.		
r			1 0		
15.4 lineal feet earth exc. at, 30cts.	4	62	47.50 lineal feet earth excavated at, 30cts	14	25.
lineal feet rock exc. at cts.			lineal feet rock excavated at cts.		
1.5 // lineal feet lead pipe at Jucts.	1	05	·lineal feet lead pipe at cts.		
incar root read pipe any 2 cost	1		Thear recovered pipe at		
12.91 lineal feet iron pipe at 64cts.	0	11	48,18 lineal feet iron pipe at .54cts.	211	0,1
12.79 inlear feet from pipe at 0 7 cts.	0	20	of the mean feet from pipe at . O / cts.	00	04
13/-1 12			61.11		
(1) Cope / Doy	2	37	Ofra depth	/	011.
	,				
A STATE OF THE STA					
<b>对是一种基本文化的</b>					
				- 5	
			Selection of the second	40.	19
			Amount charged Proprietor,		
	16	311		60	29
Amount paid by the City,	, ,		Total Cost,	0 2	1/
		2			

Lev ABriggs superintendent.

Laid for

Laid for

Mr. A. Dana

Och. 10 Street.

Blo Bedford 1870

Expense to the City, 16,30

Expense to the Proprietor, 4609

Total, - - 62,39

## Mater Registrar's Office.

New Bedford, 10/6 1870

To the Sup't of the N. B. Water Works:

Please put in a service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

OHER and and fragistrar.