New Bedford Water Works.

No. 744

RETURN OF SERVICE PIPE.

ESTATE No. 196 Street, for

Sund March

Put in by Gford Clean

Service Pipe 3/2 inches diameter.

Out of the service Pipe 3/2 inches diameter.

Cost to be paid by the City.			Cost to be paid by the Proprietor.		
			The state of the s		
27.5 lineal feet earth exc. at 23cts.	6	33	13.— lineal feet earth excavated at 23 cts.	2	99.
lineal feet rock exc. at cts.			lineal feet rock excavated at cts.		
26.5 lineal feet lead pipe at 2cts.	19	08	5.— lineal feet lead pipe at 12 cts. 9.82 " " 38	3	60. 13.
lineal feet iron pipe at cts.			lineal feet iron pipe at cts.		
Stop Tox	2	30			
2					
	/				
	1				
			Amount shound Drawitter	\$10	32
*	0 ~	7,	Amount charged Proprietor,	38	12
Amount paid by the City,	2/	//	Total Cost,	00	0 3

Israel C. Comish superintendent.

SERVICE PIPE, No. 744 Laid for. Frank Paul 136 Hind Street. July 17 1871 Expense to the City, 27.7/ Expense to the Proprietor, 10.32 -38.03 Total,

Water Registrar's Office.

New Bedford, 1971871

To the Sup't of the N. B. Water Works:

Please put in a service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.