

New Bedford Water Works.

No. 778

RETURN OF SERVICE PIPE.

ESTATE No. 111

Third

Street, for

David S. Bliss

Put in by

Gifford & Allen

Service Pipe $\frac{5}{8}$ inches diameter.

July 17

187 /

Cost to be paid by the City.

Cost to be paid by the Proprietor.

16 lineal feet earth exc. at 23 cts. 3 68.

3.5 lineal feet earth excavated at 23 cts.

8 / .

lineal feet rock exc. at cts.

lineal feet rock excavated at cts.

15 lineal feet lead pipe at 72 cts. 10 80.

2.16 lineal feet lead pipe at 72 cts.

1 56.

lineal feet iron pipe at cts.

lineal feet iron pipe at cts.

Stop Box 2 30.

3.5 ft extra trench

at 23

8 /

8 ft extra trench

at 23 184.

Amount charged Proprietor,

3 18.

Amount paid by the City,

18 62.

Total Cost,

21 80.

+ 120

Israel C. Cornish Superintendent.

SERVICE PIPE, No. 778

Laid for

David S. Bliss

111 Third Street.

July 17 1871

Expense to the City, 18.62

Expense to the Proprietor, 3.18

Total, - - - 21.80

Water Registrar's Office.

New Bedford, July 15 1871

To the Sup't of the N. B. Water Works:

Please put in a service at the estate
named on the back of this Order and
return the expense thereof, &c., to my
Office.

Jas B. Ligon
Water Registrar.
by D. B. Ligon