New Bedford Water Works. No. 876

RETURN OF SERVICE PIPE.

Estate No. Cor Union + Forth. William G. Blackler	Street, for
William G. Blackler 1	Prinama Hall)
Put in by Tillace & allen	
Service Pipe 3/4 inches diameter. Oct. 20	187/

Cost to be paid by the City.			Cost to be paid by the Proprietor.		
S lineal feet earth exc. at 2 3cts. lineal feet rock exc. at cts.	4	14.	lineal feet earth excavated at 23cts. 3 " " " extra 23 " lineal feet rock excavated at cts.		46.
lineal feet lead pipe at 73cts.	122	24.	2.83 lineal feet lead pipe at 72 cts.	2	04.
lineal feet iron pipe at cts.			lineal feet iron pipe at ets.		
Stop Box	2 3	30			
			Amount charged Proprietor,	3	19.
Amount paid by the city,	180	8	Total Cost,	2/	87.
20	9	120	rel Comish super		
From Pope on Fromth	S/a	100	an Common Super	rintend	ent.

SERVICE PIPE, No. 876

Laid for

MMG. Blackler

Forth Funion street.

Cel: 20 1871

Expense to the City, 1868

Expense to the Proprietor, 3.19

Total, - - 21.87

Water Registrar's Office,

New Bedford, 10/14 1871

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

PHHowl and J.