

APPLICATION No.: 1009

TAP CLEARED

LOCATION: 20-22-24-26 Union

OWNER: Bessie Esther

MEASURES: $\frac{1}{2}$ "

N x S	Union	4.4 ft.
E from W	Front	4.5 ft.

Additional measures (relocated service)

E x E line Bldg.	3.3 ft.
N x N line Bldg.	5.4 ft.

May 8,, 1973 Installed anew 1" service from the main
on Union St. to the curb stop.

The old service coming off Front St. was abandoned.
22½ ft. - 3/4" Copper tubing 3/4" Hays corporation
Caldwell Stop Box

October 31, 1960 Renewed from $\frac{1}{2}$ ft. outside curb stop to meter inside the building.

10 $\frac{1}{2}$ ft. of 3/4" copper tubing 1 3/4" cop. to cop. stop
1 lb. wiping solder

May 20, 1970 Renewed from the main to a point 4 ft. from the main.
4 ft. of 3/4" copper tubing 1 3/4" x 3/4" Hays corp. cplg.
1 wipe joint

July 5, 1961 Renewed from main to curb stop
13 ft. of 3/4" copper tubing 1 reused corp. cplg.

[illegible]

CHARGE OUTS.

[illegible]

P 47 L 41

APPLICATION No.: 33759

TAP CLEARED

LOCATION: 24 Union St

OWNER: 24 Union St LLC

31-313

MEASURES: Contractor: Kirk Franklin

2" Copper 11-09-2012

S from S line Union St 16.0

E from E line Front St 12.9

S from N line Building 16.0

N from S line Building 37.0

E from E line Building 12.9

Main to Property Line 20.0

Pipe inside Property 5.0

11/9/12 - Frank Corp laid new water service 11/9/12

Inspector: Percy Reynolds

DATE

BEF.

AFT.

REMARKS

[illegible]

Plot 47 Lot 41

APPLICATION No.: 33760

TAP CLEARED

LOCATION:

24²⁰ Union St

OWNER:

24 Union St LLC

FIRE SUPPLY

31-313

MEASURES:

Contractor: Kirk Franklin

6" Ductile Iron - F.S. 11-09-12

S from S line Union St 14.2 ft

E from E line Front St 17.0 ft

S from N line Building 14.2 ft

N from S line Building 36.2 ft

E from E line Front St 17.0 ft

Main to Property Line 20.0 ft

Pipe from Inside Property 5.0 ft

11/09/12 -Frank Corp laid 6" fire supply on 11/9/12
Inspected by Percy Reynolds

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]