. 10/9/2007 Killed ServiceAPPLICATION No.: 10811	TAP CLEARED					
LOCATION: 525-7 So. Second St.	DATE	BEF.	AFT.	REMARKS		
OWNER: Jose Pilar						
H lead July 25, 1904						
W from Second St. 52.0 ft.						
			4			
S From N line Delano St. 7.9 ft.						
MEASURES: H lead July 25,1904 W from Second St. 52.0 ft. S from N line Delano St. 7.9 ft. E from Wline bldg. 4.8 ft.						
1/12/79-Renewed 6" outside to 3.6' inside curb stop.						
4 ft3/4" dopper; 2-5/8" x 3/4" le ad-cop. adapt. XXS; 3/4" curb stop; Caldwell stop box;						
374 curb stop, cardwerr stop box,						
BRADBURY-WARING, INC.						

METER HISTORY									CHARGE OUTS					
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST		TEST		TEST			REMARKS	
	OUT													
10-18-6	7	= /0	Hansar B	3623224				-						
10-10-0		5/ 6	Hersey F	3523224										
								111111111111111111111111111111111111111	一大大生 一					
		7												
					No.		1. 3							
					1 48									
								8 1						
								18						
										and the second second				
						-								
								A						
								Wiley.						

10/9/07 Killed Service APPLICATION No.: 10811		TAP CLEARED			
10/9/07 Killed Service APPLICATION No.: 10811 LOCATION: 61 Delano St.	DATE	BEF.	AFT.	REMARKS 2	
• OWNER:	7-23-07		12:00	2007-290-6616	
MEASURES:					
MEAGORES.	F				
7."			Marie Control		
W from So. Second 52.0					
S from N line Delano 7.9 E from W line Bldg. 4.8					
				*	

METE	METER HISTORY								CHARGE OUTS	
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
	001									
							-			
								1		
		711								
						-				
		7 14								