

45

APPLICATION No.: 11236

TAP CLEARED

LOCATION: 99 Maple

OWNER: Leo Kenny

MEASURES: 5/8"

Copper

11-24-2005

E from E line

Park

137.8 ft.

S from N line

Maple

9.1 ft.

W from E line

House

4.5 ft.

DATE

BEF.

AFT.

REMARKS

8/11/98

98322296

8-11-98 Tap reamed

6-28-2000 Tap reamed

6-27-2000 Tap reamed

8-11-98 Renewed from main to a point 1 ft. Stock: 1 ft - 3/4" Copper tubing, 1 - 5/8" x 3/4" lead to cop. adapt. SX, 1 - 5/8" x 3/4" Fig. 413.

6-28-2000

Stock: 14 ft. - 3/4" Copper tubing, 1 - 5/8" x 3/4" lead to cop. adapt. XS, 1 - 5/8" x 3/4" Fig. 413. Zenone to maintain cut.

6-27-2000 Renewed from main to a point 14 ft. Stock: 14 ft. - 3/4" Copper tubing, 1 - 5/8" x 3/4" lead to cop. adapt. XS, 1 - 5/8" x 3/4" Fig. 413. Zenone to maintain cut.

9-4-12 - Picked up 3/4" couplings + blank

8/29/12 - WC Smith & Sons renewed this water service from curb stop to meter. Inspected by Percy

New ADDITIONAL MEASURES

E from W line House

21.0

S from S line House

19.0

Main to Property Line

32.0

Pipe inside Property

16.0

Owner charged \$115 (\$45 Shut-off + \$70 Inspector fee)



[illegible]

## This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and small dark spots, possibly due to age or handling. A faint horizontal line is visible near the top edge, and a small dark mark is present in the lower-left quadrant.