| APPLICATION No.: 11736 | TAP CLEARED | | | | |
|--|-------------|------|------|---------|--|
| LOCATION: 104 Winsor | DATE | BEF. | AFT. | REMARKS | |
| OWNER: John Almeida | 12/11/ | 73 | | Reamed | |
| MEASURES: 그해 | | | | | |
| | | | | | |
| W from Crapo 72.8 ft. N from S Winsor 9.0 ft. | | | | | |
| W from E barn 2.0 ft. | | | | | |
| December 11, 1973 Renewed from the main to inside bldg. | | | | | |
| 23 ft 3/4" Copper tubing (5 ft. inside) 3/4" Curb Stop 3/4" x 3/4" Fig. 413 | | | | | |
| 3/4" Curb Stop 3/4" x 3/4" Fig. 413 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | , | | | | |
| | | | | | |
| | - | | | | |
| | | | | | |

| METER HISTORY | | | | | | | | | |
|---------------|-----|------|--------|--------|---------|------|--|---|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | TEST | | REMARKS | |
| 5/1/47 | | 5/8 | Hersey | 533882 | | | | | |
| | | | | | | | | | |
| | | | | | 0 | | | | |
| | | | | | 9 | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | 7 | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | San | |