OWNER: John G. Edge  MEASURES: 5/8"  W from Baylies 67.6 ft. S from N Wood 9.5 ft. W from E house 2.4 ft.  1-30-98 M. Pavao renewed service from the main to the property line. 3/4" Copper tubing, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8"x3/4" lead to cop adapt. Information rec'd from Tibbets Eng.  8/29/12 - City crew renewed water service from curb stop to meter 18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's foreman: Jarred Medeiros		APPLICATION No.: 12123		TAP	CLEAR	RED \
MEASURES: 5/8"  W from Baylies 67.6 ft. S from N Wood 9.5 ft. house 2.4 ft.  1-30-98 M. Pavao renewed service from the main to the property line. 3/4" Copper tubing, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8"x3/4" lead to cop adapt. Information rec'd from Tibbets Eng.  8/29/12 - City crew renewed water service from curb stop to meter 18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's	LOCATION: 307 Wood		DATE	BEF.	AFT.	REMARKS
W from Baylies 67.6 ft. S from N Wood 9.5 ft. W from E house 2.4 ft.  1-30-98 M. Pavao renewed service from the main to the property line. 3/4" Copper tubing, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8"x3/4" lead to cop adapt. Information rec'd from Tibbets Eng.  8/29/12 - City crew renewed water service from curb stop to meter 18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's	OWNER: John G. Edge					
S from N Wood 9.5 ft. W from E house 2.4 ft.  1-30-98 M. Pavao renewed service from the main to the property line. 3/4" Copper tubing, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8"x3/4" lead to cop adapt. Information rec'd from Tibbets Eng.  8/29/12 - City crew renewed water service from curb stop to meter 18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's	MEASURES: 5/8#	opper 05/21/2008	8/24/12			2012-3404787
line. 3/4" Copper tubing, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8"x3/4" lead to cop adapt. Information rec'd from Tibbets Eng.  8/29/12 - City crew renewed water service from curb stop to meter 18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's	S from N	Wood 9.5 ft.				
stop to meter  18 ft -3/4" copper tubing; 1 -3/4" curb stop; 1 Caldwell  stop box - also repaired section of sewer service  damaged while working on water service  7 ft - 6" PVC pipe; 2 -6" straight fernco's	line. 3/4" Copper tubi	ng, 1-3/4" Curb Stop, 1-Stop Box, 1-5/8'	y "x3/4"			
stop box - also repaired section of sewer service damaged while working on water service 7 ft - 6" PVC pipe; 2 -6" straight fernco's	stop to meter					
foreman: Jarred Medeiros	stop box - also rep	paired section of sewer service ing on water service	dwell			
	foreman: Jarred Me	edeiros				
						/

METE								1000	
DATE	SET OUT	SIZE	MAKE	NUMBER	READING		TEST		REMARKS
1.100		- 10							
1/4/62		5/8	Hersey	1757874		-			
						-			
						-			
						-			
						-	-		
						-	-		
						-		-	
		-				-			
							-		
						+			
			11			-			
						+	-		
k nfill									
						-			
						-			
		-				-			
						-			
						-			
						-			
		1				-			
						-			
						-			