

APPLICATION No.: 12415

TAP CLEARED

LOCATION: 164 Rockland St

OWNER:

31-313

MEASURES:

1" Copper Service
10/24/2018 Lead Service Replacement Program
Phase 1, Contractor P Gioioso & Son
Type CU, Diameter 1in, Water pressure 90
Distance from main to curb stop (Ft) N/A
Distance from curb stop to meter (ft) 23
Distance from curb face to curb stop (ft) 2
Depth of service (ft) 4.5
Total length of new pipe installed (ft) 23
Curb stop replaced: No
Corporation replaced: No
Ball valve replaced: Yes size 1"

DATE

BEF.

AFT.

REMARKS

[illegible]

29

APPLICATION No.: 12415

TAP CLEARED

LOCATION: 164 Rockland St.

OWNER: Antone Sylvia

MEASURES: 5/8" H lead Nov. 5, 1908

E from Bolton Rd. 66.6 ft.

N from S line Rockland St. 7.0 ft.

E from W line House 13.4 ft.

Feb 7, 1997: Renewed from main to a point 8 in.

Stock: 8 in. 3/4" copper tubing 1-3/4x5/8 lead-cop adapt.xxs

1- 3/4x5/8 Fig 413 =====

11-30-2000 Renewed from 1/2' outside curb stop to a point 1 ft.

3 inches. Stock: 1.9ft. - 3/4" Copper tubing, 1 - 3/4" Curb

Stop, 1 - Caldwell Stop Box, 2 - 5/8" x 3/4" lead to cop. adapt.

TMS

BIG BOULDER PER GREENHUT - DID NOT GO TO HATE.

3-26-01 Renewed from main to curb stop. Stock;

6 ft. - 3/4" Copper tubing,

6/22/01 Checked punch 12 ft. punch - Owner cannot seal house until lead is replaced.

Plumber said it is ready to burst. Mario was there to read meter - says nothing is wrong.

DATE

BEF.

AFT.

REMARKS

2/7/96

97060324

2/7/97: tap reamed

11/30/00 20004905783

11/00

20011203635

[illegible]

CHARGE OUTS

[illegible]