

APPLICATION No.: 13507

## TAP CLEARED

LOCATION: 1 HOWLAND TERRACE

OWNER:

MEASURES: 3/4"

W X HOWLAND TERRACE	29.5 ft
N x S line CHERRY ST	5.4 ft
E x W line HOUSE	13.2 ft

May 3, 1996:

Renewed from 1/2' outside curb stop to ins. cellar (5ft ins.  
prop line) Stock: 10ft 3/4" copper tubing same curb stop  
1- Caldwell stop box

CUT

GAVE TO TILCON

8/28/96 - ON PRIORITY LIST

DATE

BEF.

AFT.

REMARKS

5/3/96

961807659

[illegible]

## CHARGE OUTS

[illegible]

APPLICATION No.: 13507

## TAP CLEARED

LOCATION: 1 Howland Terrace

OWNER:

MEASURES: W x Howland Terrace 29.5  
N x S line Cherry St. 5.4  
E x W line House 13.2

8-28-62 Renewed from  $\frac{1}{2}$ ' outside curb stop to proper line Whelan  
 $6\frac{1}{2}$ ' of  $\frac{3}{4}$ " copper tubing type K, soft Jakusik  
1  $\frac{3}{4}$ " cop. to cop. stop, fig. 415 R.H.  
2 lbs. of wiping solder  
2 St. cut: 4' x 2' cement - 2' x 2' dirt

9/24/79: Franklin renewed service from the main to the  
curb stop

8 ft. -  $\frac{3}{4}$ " copper  
1- $\frac{3}{4}$ " curb stop  
1-Caldwell stop box  
1- $\frac{5}{8}$ " x  $\frac{3}{4}$ " Fig. 413

*Called 1/25/88 Water going in  
cellar.*

*1/12/96 no leak found R. Smalley*

*1/24/96 DIAS Plumber called*

DATE

BEF.

AFT.

REMARKS

5/3/96

961807659



[illegible]

## CHARGE OUTS

[illegible]