

13526

APPLICATION No. 13526

TAP CLEARED



LOCATION:

126 Princeton St (SS) E x Arlington St

DATE

BEF.

AFT.

REMARKS

OWNER:

31-313


MEASURES:

3/4"

Copper

E from E line Arlington St	112.0
N from S line Princeton St	7.0
W from E line House	9.0
E from W line House	19.3
N from N line House	21.0
Main to Property Line	18.0
Pipe inside Property	25.0

7/27/10 - Nelson Cardoso renewed service from curb stop to meter. Owner charged \$160 (\$45 -shutoff; \$70 inspection & \$45 turn-on). Inspected by Percy Reynolds
New measures listed above



[illegible]

CHARGE OUTS

APPLICATION No.: 13526

LOCATION: 126 Princeton S.S., E. of Arlington

OWNER: Bruno Charbonneau

MEASURES:	5/8"	L lead	7-15-1910
	E from	Arlington	111.5 ft.
	N from S line	Princeton	7.7 ft.
	W from E line ^{1/5}	House	8.9 ft.

December 2, 1957 Renewed from a point $\frac{1}{2}$ ft. outside curb stop to property line.

9 ft. of 3/4" copper tubing 1 3/4" copper stop
2 lbs. wiping solder

January 30, 1970 Renewed from the main to a point $8\frac{1}{2}$ ft.
 $8\frac{1}{2}$ ft. of $3/4$ " copper tubing 1 wiped joint
 1 $3/4$ " x $3/4$ " Hays fig. 413

Feb 17, 1996: Renewed from main to prop line

Stock: 20ft 3/4" copper tubing 1-3/4" curb stop

1- Caldwell stop box 1-3/4x5/8 lead-cop adapt.xs

1 - $3/4 \times 5/8$ Fig 413

TAP CLEARED

DATE _____

BEF.

AFT.

REMARKS

1-30-70

2/17/96

2/17/96: tap reamed

Reamed

960 702617

reamed

[illegible]

CHARGE OUTS

[illegible]