	APPLICATION No.: 13845	TAP CLEARED 7				
LOCATION: 105 Rockdale Ave.		DATE	BEF.	AFT.	REMARKS	
· OWNER: Sharp M Glass						
6"						
MEASURES: 6" Chap gate	Hamlank 77 2 64					
S from N line	Hemlock 73.2 ft. Rockdale 13.9 ft.					
E from W line	Storehouse 6.7 ft.			- 3		
Aug. 27, 1982 During cement	lining - tapped 6" domestic					
service #13845 and found not	in use.					
Left 6" x 2" Service Saddle also, 6" gate valve was left	6. 6" x 2" Service saddle					
This service is not in use						
Measures of 6" x 2" Saddle						
S x N line Rockdale Ave.	10 ft.					
W x W line Hemlock St.	76 ft.					
				1. 1912		
		/				
					/	

			PRY						CHARGE	0013	-
DATE SET SIZE		MAKE	NUMBER	READING	TEST		REMARKS		B . 7 .	7	
OUT				1 17	7-19			1			
6-23-55		1"	Hersey H F	3104240							
		-									
		-			*						
						-					
	-	-									
						-					
	+										
	_										
		-									
	-	-									
	+	-									
3											
	-	1									