

APPLICATION No.: 13846

TAP CLEARED ✓

LOCATION: 105 Rockdale Ave.

OWNER:

MEASURES: 10"

FIRE . SUPPLY

10" Chap gate wooden box

W from Hemlock 71.0 ft.

S from N line Rockdale Ave. 13.9 ft.

E from W line Storehouse 8.9 ft.

Aug. 27, 1982 During cement lining tapped 10" service #13846 for by-pass. The 10" x 2" service saddle with 2" tap left in shut off position. Saddle left in ground & plugged.

Location of 10" x 2" Saddle: S x N line Rockdale Ave.
W x W line Rockdale Ave.

10 ft.

70 ft.

Stock: 10" x 2" Service Saddle 2" Corporation tap
2" Plug.

- - -

[illegible]

CHARGE OUTS

[illegible]

APPLICATION No.: 13845

TAP CLEARED

LOCATION: 105 Rockdale Ave.

OWNER: Sharp M Glass

MEASURES:

6"

6" Chap gate

W from gate

S from N line

E from W line

Hemlock

Rockdale

Storehouse

73.2 ft.

13.9 ft.

6.7 ft.

Aug. 27, 1982 During cement lining - tapped 6" domestic service #13845 and found not in use.
Left 6" x 2" Service Saddle with 2" tap shut off position also, 6" gate valve was left shut off.

This service is not in use. - 6" x 2" Service saddle
2" Corporation tap

Measures of 6" x 2" Saddle:

S x N line Rockdale Ave. 10 ft.

W x W line Hemlock St. 76 ft.

- - -

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]