APPLICATION No.: 14020		TAP	CLEARE	D
LOCATION: 143 - 145 Fair St	DATE	BEF.	AFT.	REMARKS
OWNER:		,		
MEASURES: April 10,1911  N X Fair St E X W line Sears St N X N line House  1" Copper Service				
10/02/2018 Lead Service Line Replacement Program Phase 1, Contactor P Gioioso & Son Type CU, Diameter 1in, Water pressure 100 Distance from main to curb stop (ft) 24 Distance curb stop to meter (ft) 19 Distance from curb face to curb stop (ft) 1.5 Depth of service (Ft) 4.5 Total length of new pipe installed (ft) 43 Curb stop replaced: yes size 1" Corporation replaced: yes size 1" Ball valve furnished: yes size 1"				
143 Fair St Date: 9/22/2016 Contractor: Riley Brothers Service Hit, repaired by DPI Cop- ¾ Box of Copper Tubing Units 3 UOM Feet LCXXS – 5/ 5/8" to ¾" Lead to Copper 8 x ¾ coupling XXS Units 2 UOM Each CSValve – ¾" Curb Stop Valve ¾ Units 1 UOM Each				

METER HISTORY										CHARGE OUTS		
DATE	SET	SIZE	MAKE	NUMBER	READING	T	EST		REMARKS			
							1					
			N	#145 F	( 11) E WA	25	S S S S S S S S S S S S S S S S S S S		Solve College			
							+					
							_		THEST	TOTAL LAND		
							1					