

APPLICATION No.: 14308

TAP CLEARED

LOCATION: 27 SIDNEY ST

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

OWNER: ERNEST VIEIRA ET UX

2/11/94: tap reamed

31-313

MEASURES: 5/8" H LEAD AUG.3,1911

W from BOLTON ST 247.5ft

S from N line    SIDNEY                      9.4

E from W line HOUSE 12.6

2/11/94: Renewed from main to a point 1ft in front of main  
Stock: 1ft 3/4" copper tubing 1-3/4x5/8 lead-cop adapt.xxs  
1-3/4x5/8 Fig 413

=====

12/06/13 City crew renewed service from main to curb  
stop

Stock: 25ft - 3/4" copper tubing; 1 - 3/4" curb stop;  
1 - Caldwell stop box; 1 - 5/8"x3/4" Fig 413; Tap  
reamed / R. Aguiar

R. Aguiar

-----

[illegible]

## CHAR E OUTS

[illegible]

APPLICATION No.: 14308

TAP CLEARED

LOCATION: 27 Sidney St.

OWNER: Ernest Vieira, Et Ux

"OK ELECTRIC"

MEASURES:

5/8"

H lead

Aug. 3, 1911

W from

Polton St.

247.5 ft.

S from N line

Sidney St.

9.4 ft.

E from W line

house

12.6 ft.

DATE

BEF.

AFT.

REMARKS

2-10-94

9406 02040

-----  
 November 21, 1967 Renewed from  $\frac{1}{2}$  ft. outside curb stop to inside of the cellar.

18 ft. of  $\frac{3}{4}$ " copper tubing used. Total.

9 ft. of  $\frac{3}{4}$ " copper tubing from  $\frac{1}{2}$  ft. outside curb stop to line.

9 ft. of  $\frac{3}{4}$ " copper tubing from Property line to inside cellar.

1  $\frac{3}{4}$ " curb stop. Mueller

1 wipe joint

mis mello 99418813006

3/4/91 Rusty Water Took color sample clear 2 casts

3/5/91 Took another sample 2nd floor clear

Called Mayor's office about problem gave her bottle of rust remover

[illegible]

## CHAPTER 10