

X1103

APPLICATION No.: 14782

TAP CLEARED

LOCATION: ~~1105~~- Shawmut Ave.OWNER: Incinerator

MEASURES: 6" & 8"

FIRE

SUPPLY

N from

Hathaway Rd.

162.0 ft.

E from W line

Shawmut Ave.

104.0 ft.

SE from Center of hydt. 1635 .4

15.0 ft.

N from

Hathaway Rd.

 March 16, 1959 Repaired leak in $1\frac{1}{2}$ " brass pipe by installing a
 $1\frac{1}{2}$ " mechanical iron coupling 20.5 ft. W x $1\frac{1}{2}$ " controlling gate
 valve in wooden box:

1 $1\frac{1}{2}$ " Style 90-1 Regular steal cplg., fig. 82 for steel

August 8, 1962 Installed 8" x 6" reducer in West 8" main cross;
 removed 2 sets of check valves; and installed $5\frac{1}{2}$ ft. of 6" pipe
 to fill in where checks were removed.

1 8" x 6" reducer, bell & spigot, cement lined

$5\frac{1}{2}$ ft. of 6" cast iron cement lined pipe

21 lbs. leadite

$1\frac{3}{4}$ lbs. braided jute

2/15/80: 1" Service: Installed a 1" curb stop; 4 ft.-
 1" copper; 1" curb stop; Caldwell stop box; 1" x 1" cop.
 cop. Comp. Cplg.

4/6/87 T.O. 1" SERVICE HAD BEEN S.O. SINCE AUG. 86

T.S.

DATE

BEF.

AFT.

REMARKS

Garbage Plant Garage:

6.0 ft. E x W line Bldg.

10.5 " S x S line Bldg.

[illegible]