

APPLICATION No.: 14895

TAP CLEARED

LOCATION: 100 Rockland St

OWNER:

31-313

MEASURES: 1" Copper Service

10/29/2018 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, Diameter 1in, Water pressure 90

Distance from curb stop to main (ft) N/A

Distance from curb stop to meter (ft) 17

Distance from curb face to curb stop (ft) 2

Depth of service (ft) 3.7

Total length of new pipe installed (ft) 17

Curb stop replaced: No

Corporation replaced: NO

Ball valve replaced: Yes size 1"

DATE


BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS



APPLICATION No.: 14895

TAP CLEARED

LOCATION: 100 Rockland St.OWNER: Jos. J. P. Carreiró, Et Ux

DATE BEF. AFT. REMARKS

5/17/96: tap reamed

MEASURES: 5/8" H lead Sept. 6, 1912W from Crapo St. 30.0 ft.N from S line Rockland St. 6.9 ft.W from E line house 2.5 ft.

Feb. 25, 1977 Renewed from 6" outside curb stop to the property line.

7½ ft. - 3/4" Copper tubing

3/4" curb stop Caldwell Stop Box

2 - 5/8" x 3/4" lead to copper adaptor XS

May 17, 1996: Ch.90 reconstruction

Todesca Corp renewed service from main to curb stop

Cont. supplied all stock & will maintain trench

9.5ft 3/4" copper tubing 1-3/4" curb stop

1- Caldwell stop box 1-3/4x5/8 Fig 413

NOTE: W/D NO INSPECTION PER F BENTO

[illegible]

CHARGE OUTS.