

APPLICATION No.: 15085

TAP CLEARED



LOCATION: 6 Stapleton

v

OWNER: John Ventura

MEASURES:

5/8"

N from

Brock Ave.

66.0 ft.

W from E line

Stapleton

9.0 ft.

N from S line

Body House

9.0 ft.

 July 29, 1963 Renewed from $\frac{1}{2}$ ft. outside curb stop to $3\frac{1}{2}$ ft. inside the curb stop.

4 ft. of $\frac{3}{4}$ " copper tubing 1 $\frac{3}{4}$ " cop. to cop. stop

2 lbs. wiping solder

Note: This service was broken by Perini equipment while digging for house drains.

 August 23, 1963 Renewed from the main to the property line.

36 ft. of $\frac{3}{4}$ " copper tubing 1 $\frac{3}{4}$ " cop. to cop. stop

1 Caldwell stop box, complete-long 1 lb. wiping solder

1 $\frac{5}{8}$ " reused corporation coupling

 1" Copper Service

4/25/2019 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, DIameter 1in, Water pressure 100

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 23.5

Distance from curb face to curb stop (ft) 3

Depth of service (ft) 4

Length of new pipe installed (ft) 23.5

(curb stop replaced: no corporation replaced: no

h Ball valve furnished: yes Size 1"

METER HISTORY

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS
11-21-63		5/8	Trident	16811245					

CHARGE OUTS

