| | | TAP CLEARED | | | | | | |
|---|---|--------------------|-------------|------|--------------|------|---------|---|
| LOCATION:_ | 57 Jenney | | | DATE | BEF. | AFT. | REMARKS | 0 |
| OWNER: _ | Violet Atwood | | | | | | | |
| MEASURES: | 5/8" | | 1-1-1914 | | | | | |
| | N from | Elm | 77.0 ft. | | | | | |
| | E from W line | Jenney | 5.5 ft. | | | | | |
| | S from N line | House | 8.0 ft. | | | | | |
| 9/18/08 - De cellar - cur Water Rehab | | | | | | | | |
| Inspected by | Manny Rose | TO INSPECTION TEE | | | | | | |
| 9-18-08 - Ne | w measures: | | | | | | | |
| | N from N line | Elm St | 79.0 | | | | | |
| | E from W line N from S line | Jenney St house | 5.0 15.0 | | | | | |
| | S from N line | House | 8.0 | | | | | |
| | E from E _ine | House | 5.0 | | | | | |
| | Main to property line Pipe inside property | | 12.0 | | | | | |
| | | | 0.0 | | | | | |
| 9/17/08 - W | rina Const. | | | | | | | |
| Renewed ser | | | | | | | | |
| | copper tubing; 1 - 1" o | | | | The state of | | | |
| Inspected by | y Tim Ives, CDM | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| METER HISTORY | | | | | | | | CHARGE OUTS | |
|---------------|-----|------|-------------|----------|---------|--|------|-------------|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | REMARKS | |
| 1-7=64 | | 5/8 | Trident Mag | 16811727 | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | , | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | , | | | | | | | |