

APPLICATION No.: 15953

## TAP CLEARED

LOCATION: 52 Rotch S.E. Cor. Clinton

DATE

BEF.

AFT.

REMARKS

OWNER: Evelyn McIntosh

7-23-68

Reamed

MEASURES: 5/8"

E from	Rotch	47.0 ft.
N from S line	Clinton	7.0 ft.
W from E line	House	2.0 ft.

-----  
August 14, 1968 Repaired leak at inside flare coupling of curb stop  
-----

July 23, 1968 Renewed from main to property line.

13 ft. of 3/4" copper tubing used. Total

1 3/4" fig. 413 1 3/4" curb stop. Mueller

1 wipe joint- 1 Buffalo stop box, complete-long

Old stop box broken, and pieces returned to the repair shop for scrap.  
-----

3-31-2000 Renewed from main to property line. Stock:

12 ft. - 3/4" Copper tubing, 1 - 3/4" Curb Stop,

1 - Caldwell Stop Box, 1 - 3/4" x 3/4" lead to cop  
cplg., comp. Silva Const. to maintain cut.

[illegible]

## CHARGE OUTS

[illegible]



APPLICATION No.: 15954 C

TAP CLEARED

LOCATION: Rear 52 Rotch S.E. Cor. Clinton

OWNER: \_\_\_\_\_

MEASURES:  $5/8"$

Conn made by Owner using about 20 ft.  $5/8"$  L lead pipe

$2\frac{1}{2}$  lbs. per foot.

Conn of Appli# 15953.

INACTIVE  
SERVICE

DATE

BEF.

AFT.

REMARKS

[illegible]

## CHARGE OUTS

[illegible]