

APPLICATION No.: 16091

TAP CLEARED

LOCATION: 68 Hussey Cor. Kempton

OWNER: Jos H Terrall

MEASURES:

S from	Kempton	22.8 ft.
W from E line	Hussey	8.6 ft.
S from N line	house	7.8 ft.

DATE

BEF.

AFT.

REMARKS

12-1-99

Tap reamed

12-1-99 1999 4903656

5/8" Leak inside of cellar Meter Room 11/29/90
 Located and cleared Stop Box Regulator 11/29/90

Feb. 6, 1991

This service was renewed from a point 2'6"
 inside curb stop, to inside the cellar by Frank
 Corp. There was a leak inside the cellar.

Contractor cemented the sidewalk cut.

Stock supplied by Contractor:

17 ft. - 3/4" Copper tubing

1 - 5/8" x 3/4" lead to copper adapt XS

12-1-99 Renewed from main to curb stop to a point 6 ft.

ins. curb stop. Stock: 25 ft. - 3/4" Curb Stop,

1 - Caldwell Stop Box, 1 - 3/4" x 3/4" cop to cop

cplg., comp. , 1 - 5/8" x 3/4" Fig. 413.

[illegible]

CHARGE OUTS

[illegible]