APPLICATION No.: 16101		ТДР	CLEAR	PED
OCATION: Purported 121 North St	DATE	BEF.	AFT.	REMARKS
OWNER: 0. 58 L. 259 A MEASURES:	Mary and a second	-		
Contractor Farland Corp renewed and relocated service from curb stop in. 07.05.2023 Inspector Percy Reynolds 2" Copper E X E Line Summer St 55.6' S X N Line North St 5.2' E X W Line Building 39.5' S X S Line Building 19' Pipe Inside property 20'				
			10	

METER HISTORY									CHARGE OUTS							
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		TEST		TEST		TEST		REMARKS	
	OUT			3.0			-									
	-				100000000000000000000000000000000000000											
				120												
		-														
							-									

Demestic Service APPLICATION No.: 1610 TAP CLEARED North Go: Summer LOCATION: /2 DATE BEF. AFT. REMARKS OWNER: 31-313 MEASURES: 2"Darling gate I box E from Summer St 55.0 ft S from N line North St 6.8 ft W from E line Bldg. 42.0 ft February 7, 1975 Repaired a cracked 2" cast iron service by installing a 2" Smith Bair Style 226 Repair clamp. 7 1/2" wide at a point 16.8 ft S X N line North St 2" Smith Blair Style 226 Repair Clamp November 22, 1975 renewed from the new 30" main in North St. to a point 1 ft inside property line As of this date this service is inactive but plans are to se this service at a later date. The 2" copper is now a line service only. 28 ft. 2" copper tubing 1-2" jones corp. stop, c.f. 1 – 2" hays curb stop, cf Buffalo gate box Measures: EXELine Summer St 55.6 ft E X W line School 39.5 ft S X N Line North St 4.2 ft S X S line School 18.5 ft

METER HISTORY										CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
11-30-3	-		1-	153947						
11000		2	7	100111	The second second					
										1V- 1
				5						
<u>c</u>										
									V	
			- 1							
					-					
	33/3									