LOCATION: 126 County St. 7/28/75 Remarks OWNER: Leo J. Mello 7/28/75 Reamed MEASURES: 5/8" H lead June 30,1915 S from Blackmer St. 104.9 ft. W from E line County St. 4.2! 7.8 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop eplg. 3/4" x 3/4" Fig. 413 (inside line) JAUGUST 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" x 3/4" Fig. 413 3/4" Copper eplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to hook up generator to thaw out.	LOCATION: 126 County St. DATE BEF. AFT. REMARKS OWNER: Leo J. Mello MEASURES: 5/8" H lead June 30,1915 S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.9 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) JAUGUST 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" x 3/4" Fig. 413 3/4" Copper cplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to	APPLICATION No.: 16276		TAP	CLEAR	RED 8952-0447
OWNER: Leo J. Mello MEASURES: 5/8" H lead June 30,1915 S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.8 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) Jaugust 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" x 3/4" Fig. 413 3/4" Copper cplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to	OWNER: Leo J. Mello MEASURES: 5/8" H lead June 30,1915 S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.8 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to		DATE	BEF.	AFT.	REMARKS
S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.2 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) Jaugust 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" corporation 5/8" corporation 5/8" copper cplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to	S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.8 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) Jaugust 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" corporation 3/4" Copper cplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to		7/28/	75		Reamed
		OWNER: Leo J. Mello MEASURES: 5/8" H lead June 30,1915 S from Blackmer St. 104.9 ft. W from E line County St. 4.2: 7.8 ft. S from N line garage 3.2 ft. July 28, 1975 Renewed from the main to the property line. 32 ft 3/4" Copper tubing 3/4" Curb stop Buffalo Stop Box 3/4" cop to cop cplg. 3/4" x 3/4" Fig. 413 (inside line) August 15, 1975 Repaired service broken by Contractor 7 ft 3/4" Copper tubing 5/8" corporation 5/8" x 3/4" Fig. 413 3/4" Copper cplg. January 14, 1981 Thaw out frozen service. Dec. 26, 1989 frozen service - had to dig main for tap to	7/28/		281	Reamed

METE	R H	IIST	ORY							CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	- N. T.
8/31/60		5/8	Calmet	1596277				4 4		
)						7				
D										
1			E.C.							
							4 7			
			20							

APPLICATION No.: 15619 5/8"		TAP	CLEAR	RED
LOCATION: 124 County St.	DATE	BEF.	AFT.	REMARKS
. OWNER: Robert Godber				
MEASURES: 5/8"	4-4-5			
N from Winsor 46.0 ft. W from E line County 8.0 ft.				
N from S line House 9.5 ft.				1
May 13, 1975 Renewed from a point 11 ft. W x curb stop to a point 13 ft. w x curb stop.				
2 It 3/4" Copper tubing 2 - 5/8" lead to copper				
3/4" Curb stop (temporary) _ adaptor XS				
INACTIVE SER				
110,000,000				
$\leq z_0$				
J. 617				

METE	R H	ISTO	RY						Res The Land	CHARGE OUTS
		SIZE	MAKE	NUMBER	READING		TEST		REMARKS	*
	001				Control of the Contro					The state of the s
/15/33		5/8	Lambert	96981						
						-				
-										
						-				
					1 40			1		
						-	-			
		,				-				
	7 2	- 400								
						-	-			
						-				
	-					1250				1
							-			- /
						-				
	-									
	-		142 ×15	*						
				THE RESERVE AND A SECOND						