

APPLICATION No.: 16853

TAP CLEARED ✓

LOCATION: 29 Spring

OWNER: N.B. Police Dept. Central

|           |                    |        |          |
|-----------|--------------------|--------|----------|
| MEASURES: | 3"                 | C.I.   |          |
|           | Darling gate I box |        |          |
|           | W from             | Second | 80.0 ft. |
|           | S from N line      | Spring | 6.5 ft.  |
|           | W from E line      | Bldg.  | 42.0 ft. |

-----  
 June 20, 1972 Repaired a leak on the service by using a 3" Smith Blair full circle stule 226 repair sleeve. 9.0 ft. N x tapping gate.  
 -----

June 17, 1969 Installed 2 ft. of 6" cast iron pipe into the 6" bell of the 8" x 6" tee in Spring St. for service #16853. Installed a 6" mechanical gate at the end of the 6" cast iron pipe. Installed a mechanical plug with a 3" hole tapped out in the north bell of gate. Installed a 3" brass adaptor 3" thread to 3" sweat into plug. Installed 7 ft. of 8" copper from the adapter northerly connecting to the existing copper.

|                                 |                                     |
|---------------------------------|-------------------------------------|
| 2 ft. of 6" cast iron pipe      | 1 6" mech gate (Darling) for #16853 |
| 1 6" mech plug (tapped 3" hole) | 1 3" brass adaptor                  |
| 7 ft. of 3" copper tubing       | 1 3" slip coupling (copper)         |
| 1 6" gate box, complete-long    |                                     |

Location of 6" gate for ser. #16853:

|            |            |          |
|------------|------------|----------|
| W x W line | Second St. | 79.6 ft. |
| W x E line | Building   | 14.0 ft. |
| S x N line | Spring St. | 27.4 ft. |
| S x S line | Building   | 40.7 ft. |

Work done by Campanella. Inspected by Arthur Pacheco.

-----  
 MAIN SHUT DOWN SER OFF  
 CUT OFF AT SPRING ST.

[illegible]

## CHARGE OUTS

[illegible]