

APPLICATION No.: 17030

TAP CLEARED

LOCATION: 98 West

OWNER: Edmond Barker

MEASURES: 5/8"

N from	Priscilla	27.9 ft.
W from E	West	9.0 ft.
N from S	house	3.0 ft.

-----  
 Feb. 19, 1963 Renewed from a point  $\frac{1}{2}$  ft. outside curb stop to a point 3 ft. inside the curb stop.

3 $\frac{1}{2}$  ft. of 3/4" copper tubing      1 3/4" copper to copper stop  
 2 lbs. wiping solder

-----  
 March 24, 1965 Renewed service from 1 ft. west of bend to 6 ft. west of bend.

5 ft. of 3/4" copper tubing      2 lbs. wiping solder  
 This service was broken by D.P.W. equipment. D.P.W. will maintain cut

-----  
 July 28, 1965 Renewed service from main to  $\frac{1}{2}$  ft. outside curb stop  
 21 ft. of 3/4" copper tubing      1 3/4" copper coupling

-----  
 May 5, 1965 This service was disconnected from the 1" light lead main in West St., N x Priscilla St.; and, installed into the recently installed new main pipe - 6" size - in this street.

1 3/4" corporation fig. 438      3 ft. of 3" copper tubing -  
 1 lb. wiping solder      from main to 3 ft. from main.  
 This work done while the new 6" main pipe was being installed.

-----  
 8/1/77 Renewed 3 ft. inside curbstop to inside cellar. 19 ft.-3/4" cop.  
 (12 ft.ins.); 3/4" x 3/4" cop. to cop. cplg.

DATE

BEF.

AFT.

REMARKS

[illegible]

## This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book. There is no text or other markings on the page.