

APPLICATION No.: 17303

TAP CLEARED

LOCATION: 19 JONATHAN ST

OWNER: ALFRED THADSERAY

MEASURES: $3/4"$

N FROM	ARNOLD ST	167.9 ft
E FROM W LINE	JONATHAN	8.6 ft
N FROM S LINE	HOUSE	2.7 ft

Aug 11, 1997: RENEWED from lft outside curb stop to a point lft
ins. curb stop Stock: 2ft 3/4" copper tubing 1-3/4" curb stop
1-caldwell stop box 2-3/4x5/8 lead-cop adapt.xxs (lft outside c.s.
& lft ins. C.S.)

=====

7-20-99 DW White renewed from main to property line.
Stock: 17 ft. - 3/4" Copper tubing, 1 - 3/4" Curb Stop,
1 - 5/8" x 3/4" lead to cop. adapt. XXS,
1 - 3/4" x 3/4" Fig. 413. DW White to maintain cut.

8-14-99 Renewed from property line to inside cellar.
(20 ft. ins. prop. line.) Stock: 20 ft. - 3/4" Copper
tubing, 1 - 3/4" x 3/4" cop to cop cplg., comp.

[illegible]

CHARGE OUTS

[illegible]

APPLICATION No.: 17303

TAP CLEARED

LOCATION: 19 Jonathan

OWNER: Alfred Thadseray

MEASURES:

3/4"

N from

Arnold

167.9 ft.

E from W line

Jonathan

8.6 ft.

N from S line

house

2.7 ft.

DATE

BEF.

AFT.

REMARKS

8/11/97

973300368.

9/10/90 Water was clear. Meter removed
complaining of filter getting dirty check by
J.R.

10/15/90 Complain rusty water will call plumber.

3/9/91 Sample taken outside faucet no one home
Sample clear S. Long.

6/9/97. OWNER Replaced
FILTER. PRESSURE OK. per Victor A.

[illegible]

CHARGE OUTS

[illegible]