

5-7-93 Canessa Const. cut off the 6" main & removed aling with this service. All material removed. This service was found cut off at tap-date unknown 5-7-93 Canessa Const. cut off the 6" main & removed along with this service. All material removed. This seervice was foundcut off at tap-date unknown.