

APPLICATION No.: 18190

TAP CLEARED

LOCATION: 173 Shaw St

DATE

BEF.

AFT.

REMARKS

OWNER:

31-313

MEASURES 3/4

copper 8/3/2016

renewed c/s to prop line

6 ft 3/4" copper tubing

1 ft 3/4" copper coupling

1 ft cast iron curb stop boxes

1 ft 3/4" curb stop valve

lead Worker: Rui Martins DPI

[illegible]

APPLICATION No.: 18198

TAP CLEARED

LOCATION: 173-5 Shaw N.S. E. of Concord

OWNER: Anseline Roy

MEASURES:

5/8"

E from

S from N line

E from W line

L lead

Concord

Shaw

House

9-28-21

105.8 ft.

8.6 ft.

2.5 ft.

November 14, 1951 New from tap to 1 ft. on house side of curbstop.
25 ft. of 3/4" copper tubing 1 3/4" cop. to cop. stop
1 3/4" I.P.fem. x 3/4" cop. coupling

Jan. 2, 1990 shut off for repairs
checked Dec. 26, 1990 still off

This service has been shut off for over one year and must have a new service before it can be turned on.

Street reconstruction: May 6, 1997

REnewed from curb stop to prop line

Stock: 8ft 3/4" copper tubing same curb stop

1- Caldwell stop box 1-3/4x5/8 lead-cop adpat.xs

Street reconst. renewal June 27, 1997

Renewed from 1ft outside prop line to ins.cellar (12ft ins.prop line) Stock: 13 ft 3/4" copper tubing 1-3/4x3/4 cop-cop cplg.comp

3/10/06 Service damaged by NStar Gas - Renewed from 9' outside curb
stop to 12' outside curb stop

Stock: 3' of 3/4" copper tubing, two 3/4 x 3/4 cop to cop cplg comp.

METER HISTORY

[illegible]

CHARGE OUTS