

APPLICATION No.: 18311

TAP CLEARED

LOCATION: 391 Bolton St.

OWNER: John Almeida, Jr.

MEASURES: 5/8" H lead Dec. 9, 1921

W from Bolton St. 36.4 ft.

S from N line Swift St. 7.8 ft.

E from W line bldg. 1.6 ft.

Took sample 3/1/91 clear

3/27/91 Install filter called sand filter was
black within 3 days check by Sieve Filter had a
little sign of rust particles color sample clear (Ice machine)

11/18/03 Renewed from main to inside cellar (5 ft inside property line). Stock: 38 ft 3/4" copper; 3/4" curb stop; Caldwell stop box; 5/8" x 3/4" Fig. 413 Tap reamed

11/18/03 Sewer repair Stock: 6' 18" PVC pipe; 1 - 18"
PVC-clay rubber clamp Bento

METER HISTORY

CHARGE OUTS

[illegible]