| | APPLICATION No.: 18701 | | | | | ED / |
|---------------------------------------|-----------------------------|-------------|------|--------|------|---------|
| LOCATION: 74 Jonathan St., N. o | f Union | | DATE | BEF. | AFT. | REMARKS |
| OWNER: Robert Dutra | | | | | | |
| MEASURES: 3/4# | L lead 6-1- | -22 | | | | |
| N from | Union 93.5 | 93.5 ft. | | | | |
| W from 2 line S from N line | Jonathan 10.0 house 4.8 | | | | | |
| July 21, 1951 Repaired leak | at tap. | . fem. cplg | | . 19-1 | | |
| 1½ ft 3/4" Copper tubing- | 3/4" cop x 1" i.p. fer | | • | | | |
| JDec. 16, 1971 Renewed from | the main to curb stop. | | | | | |
| 22 ft 3/4" Copper tubing | 3/4" x 3/4" Fig. 413 | | | | | |
| July 23, 1971 Renewed from | ft. outside curb sto | p to | | | | |
| property line. | | | | | | |
| 9 ft 3/4" Copper tubing 2 wipe joints | Stop Box | | | | | |
| | | | | | | |
| 1/17/07 Stop box was lowered, | blown out, and operating nu | ing nut was | | | | |
| checked by: Luis J & Derek A | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| METER HISTORY | | | | | | | CHARGE OUTS | | | |
|---------------|-----|------|------|----------|---------|------|-------------|----------|--|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | TEST | | TEST RE/ | | |
| 4-26-71 | | 3/4 | | 19128336 | 11 | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |