

7/26/06 Killed at tap & removed old c/s box Bento

Street cut: 6' x 4' Warr. S/W cut: 2' x 2' Grass

Stock: 1 - 3/4" Corporation tap 1 - 6" x 3/4" Service Saddle

Note: Water main very weak; 5/8" tap blew out off the main. (Service not in use)