	The state of the s	APPLICATION No.:	19020	TAP CLEARED 8941-1523				
LOCATION:	195 Bedfor			DATE	BEF.	AFT.	REMARKS /	
	Gordon Har		May 17	3	11	9024-0032		
MEASURES:	5/8"	L lead	Sept.26,1922	0/11/89	:TAF	REAM	D	
	W from W from W line S from N line	Waverly St. Stetson St. Bedford St.	183.4 ft. 79.3 ft. 7.0 ft.					
	E from E line	house	=5 <u>∓</u> Θ=£ŧ. 10	ft.				
15 ft. ins 15 ft 1 May 20, 19 property 1 7½ ft 1 2 wipe jo: 10/11/89 Stock:	3/4" copper tubing	Plumber() lg.  rb stop to  top Mueller;  s.	P					
6/11/90: Stock: 2	Renewed from mair oft. 3/4" copper ell stop box 1-3,3/4" service	to curb stop	curb stop tap					

METE	R H	ISTO	ORY	CHARGÉ QUTS					
DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST		REMARKS	
	001								
					*				
					,				
							, is		
								-	
									Francisco Post Control

4)	APPLICATION No.:19020		TAP CLEARED				
4	LOCATION: 195 Bedford St	DATE	BEF.	AFT.	REMARKS		
	OWNER:						
	9-1-2020: W x W line Waverly St 183.4' W x W line Stetson St 79.3' S x N line Bedford St 7.0'						
	E x E line House 10.0' S x S line House 40.0'						
	Pipe inside property 38,0' Service renewed from curb stop to meter, Contractor JLC Construction, Inspector P. Pagnolob.						
		-					

METE	METER HISTORY									CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	CHARGE OUTS
				-						