

APPLICATION No.: 19219

TAP CLEARED 85-05-012

LOCATION: 1000 Kempton S.S., E. of Oneida

OWNER: Standard Brands Inc.

MEASURES: 1"

E

from

N from S line

W from E line

Oneida

Kempton

Garage

1.0ft

35.2 ft.

~~30.7 ft.~~

42.7 ft.

Oct. 15, 1975 Renewed from the property line to
the boiler room.

25 ft. - 1" Copper tubing 1" x 1 1/4" lead to cop. adapt.

- - -

12/26/80 Thaw out frozen service

1/28/85 Renewed from main to a point 2.5 ft.

Stock: 2.5ft. 1" copper tubing 1" x 1" lead to cop adapt

comp. XXS 1 1" x 1 1/2" Fig. 413

=====

Sept 12, 1996: Renewed from main to prop line

Stock: 13ft 1" copper tubing 1-1" curb stop

1- Caldwell stop box 1-1" x 1" cop-cop cplg.comp

1- 1" x 1" Fig 413

=====

DATE

BEF.

AFT.

REMARKS

1/28/85 Tap reamed

9/11/96

963704105

9/12/96: tap reamed

[illegible]

CHARGE OUTS

[illegible]

APPLICATION No.: 19457c

TAP CLEARED

LOCATION: S.E. Cor. 1006 Kempton & Oneida

OWNER: Jane Waters

MEASURES: $\frac{3}{4}$ "

Conn. of 19219 - 1000 KEMPTON ST.

July 23, 1971 Renewed from $\frac{1}{2}$ ft. outside curb stop to a point 4 ft. inside curb stop. $4\frac{1}{2}$ ft. - 1" Copper tubing 1" curb stop
2 wipe joints

- - -

Shut off & removed in cellar 6/18/75.

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

APPLICATION No.: 19457 C

LOCATION: S.E. Cor. Kempton & Oneida

OWNER:

MEASURES: $3/4''$

Conn of 19219

INACTIVE SERVICE

TAP CLEARED

[illegible]

[illegible]

CHARGE OUTS

[illegible]