LOCATION: 538 Kirby Ct. OWNER: John T. Chambers MEASURES: 5/8" L lead N from Allen St. S from N line Aug. 18, 1966 Renewed service from 2 outside curb stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415 Iblb. wiping solder	TAP CLEARED			
MEASURES: 5/8" L lead June 14,1923 N from Allen St. 395.0 ft. W from E line Kirby St. 8.4 ft. S from N line house 1.0 ft. Aug. 18, 1966 Renewed service from 2 outside curb stop to inside cellar 252 ft. cepper tubing 1 3/4" cop.to copl stop, fig 415				
N from Allen St. 395.0 ft. W from E line Kirby St. 8.4 ft. S from N line house 1.0 ft. Aug. 18, 1966 Renewed service from 2 outside curb stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415	89			
W from E line Kirby St. 8.4 ft. S from N line house 1.0 ft. Aug. 18, 1966 Renewed service from 2 outside curb stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415				
S from N line house 1.0 ft. Aug. 18, 1966 Renewed service from a outside curb stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415	- 1			
Aug. 18, 1966 Renewed service from & outside curb stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415				
stop to inside cellar 25½ ft. copper tubing 1 3/4" cop.to copl stop, fig 415				
1 sidewalk cut: 5' x 5' cement 125 compressor: 1 hr. Abraham Breton Silva 1-19-99 Renewed from main to a point 2 ft. Stock: 2 ft 3/4" Copper tubing, 1 - 5/8" x 3/4" lead to cop.				
adapt. XS, 1 - 5/8" x 3/4"Fig. 413.				
6-30-01 Silva Const. renewed from main to curb stop. Stock by Cont. 25.6 - 3/4" Copper tubing, 1 - 3/4" Curb Stop, 1- Caldwell Stop Box, 1-5/8" x 3/4" Fig. 413. Silva Const. to maintain cut. Report by B.Donovan/CDM				
BRADBURY-WARING, INC.				

METE	R H	ISTO	CHARGE OUTS						
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST		REMARKS	
8-22-66		3/	4 Rockwell Mag	19384295					
			267						
			•						
							1 18		
						- 41			