

64

APPLICATION No.: 20033

TAP CLEARED 8842-1535

LOCATION: 48 Shawmut Ave. E.S. N. of Willis

OWNER: Robert Lacey

DATE

BEF.

AFT.

REMARKS

10/17/89: TAP REAMED

MEASURES:

3/4"

N from

Willis

130.8 ft.

W from E line

Shawmut Ave.

7.4 ft.

S from N line

House

10.4 ft.

5-3/4"

942200093

March 20, 1962 Renewed from 1/2 ft. outside curb stop to property line.

9 ft. of 3/4" copper tubing 1 3/4" cop. to cop. cplg.

2 lbs. wiping solder 1 Caldwell stop box, complete-long

April 1, 1952 Renewed from 1 ft. inside curb stop.

1 ft. of 3/4" copper tubing 1 3/4" dresser copr-tube cplg.

10/17/89: Renewed from main to inside cellar (15 ft. ins. prop line) Stock: 41 ft. 3/4" copper tubing 1-3/4" curb stop
1 - Caldwell stop box 1-3/4x3/4 Fig.413

9/29/93: service was shut off by meter room. Stop operating nut broke while shutting serv.off Installed new curb stop & box
Stock: 1-3/4" curb stop 1-Caldwell stop box

May 31, 1994 Leak at copper in cellar in meter pit. Two small holes in copper 2 ft. inside cellar wall. Cats using meter pit for litter box, urine is pitting the copper.

Installed 1 ft. pc. - copper in cellar with 2 - 3/4" x 3/4" cop to cop cplg.

Installed this before the main shut off in cellar.

1 ft. - 3/4" copper tubing 2 - 3/4" x 3/4" cop to cop cplg., comp.

[illegible]

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding structure, including what appears to be a vertical strip of material and some stitching or staples. There is no text or other markings on the page.