

**APPLICATION No.:**

43 Milton St (NS) E x Jenny Lind St

31-313

1"

Copper

## New measures

E from E line Jenny Lind St

195.7

W from Hydrant

122.0

S from N line Milton St

5.6

E from W line House

5.8

W from E line House

22.0

S from S line House

16.5

Main to Property Line

32.0

Pipe inside property

15.0

8/1/12 - Franklin Bros. renewed water service from curb stop to meter. Owner charged \$70 inspection  
Inspected by Percy

100 200 300 400 500 600 700 800 900 1000 1100 1200 1300 1400 1500 1600 1700 1800 1900 2000

TAP CLEARED

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

[illegible]

## CHARGE OUTS

[illegible]



APPLICATION No.: 20077

TAP CLEARED

LOCATION: 43 Milton N.S. E of Jenny Lind

OWNER: L. A. Whitehead

MEASURES: ~~3/4"~~ 1" now all copper

E from	Jenny Lind	195.7 ft.
--------	------------	-----------

S from N line Milton 5.8 ft.

E from W line	House	5.6 ft.
---------------	-------	---------

1/17/79: Renewed 1 ft. outside curb stop to 4.6 ft. ins. curb stop. 5.6 ft.-3/4" copper; 3/4" curb stop; 2-5/8" x 3/4" lead-cop. adapt. XXS; Caldwell stop box;

1/5/89: Renewed from main to a point 1.6 ft.

Stock: 1.6 ft. 3/4" copper tubing 1-3/4" curb stop

1 - Caldwell stop box 1-3/4x5/8 lead to cop adapt. xxs.

6/18/08 - West End Water Main Rehab Contract # 4 - Perrina Const.  
Renewed water service from main to property line

26 ft - 1" copper tubing; 1 - 1" corp tap; 1 - 1" curb stop;  
1 - 1" x 3/4" reducer. Inspected by Tim Ives, CDM

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

This leak was caused by turning curb stop on & off to check for water going into cellar. This house has a pump going constantly out in st. & into trench we made. Lady in house was told about this.

[illegible]

## CHARGE OUTS

[illegible]