

171

APPLICATION No.: 21359

TAP CLEARED 8826-0170

LOCATION: Hillman, N. S. , W. fo Ash

DATE

BEF.

AFT.

REMARKS

OWNER:

MEASURES:

6"

DeL.

8-10-1928

6" ser.I. box

W from

Ash

227.1 ft.

N from S line

Hillman

18.0 ft.

F

I

R

E

S

U

P

P

L

Y

2/3/82 Repaired leak inside bldg. S.P.F.O.D.
 5.3 ft. - 6" C.I.C.L. Ductile Pipe 2 - 6" Smith Blair
 #441 Cast Cplg.

NOTE: This fire supply is interconnected with F.S. # 21360 off
 Maxfield St. See Mill plan for dividing gate if necessary.

10/13/88 Repaired leak with 7.4 ft. of 6" ductile pipe &
 2 - 6" Romar #441 Cast cplgs.: Measures: 1] S x S line bldg. 8.0 ft.
 2] S x 1st cplg. 7.4 ft.

Main broke in street after repairs made.

10/.17/88 D .P.W. made a pit over check valve in property.

10/19/88 Repaired leak on 6" fire supply. Poured joint on the gate valve with leadite and installed
 18 ft. of 6" ductile pipe from the gate valve to existing 6" #441 cplg. (see 10/13/88 report.

CHARGE OUTS

[illegible]