LOCATION: 21 7 N.S. Downey St., W. x Mt, Pleast St. DATE BEF. AFT. R	REMARKS
OWNER: Manuel Andrade 6-23-99 Tap reamed	
MEASURES:	
3/4" HLead Aug. 24, 1943	
W from Mt. Pleasant 159.0	
S from N line Downey 7.7	
W from E line House 5.6	
Nov. 8, 1966 Renewed from main to 1½ ft. from main.	
8" X 1" saddle Dresser 1" corp 1b. wiping solder 1copper tubing used	
6-23-99 DW White renewed from main to property line.	
Stock supplied contractor: 28 ft 3/4" Copper tubing.	
1 - 3/4" Curb Stop, 1 - Caldwell Stop box, 1 - 3/4"x3/4"	
lead to cop. adapt. XXS, 1 - 1"x3/4" cop to cop cplg., comp. 1 - 1"x1" Fig. 413. DW White to maintain cut.	
11/19/01 Plumber said water coming into cellar. Checked by Augusto leak in property line under	er
foundation. 9 ft. punch	
11/20/01 Spoke w/Owner regarding renewal \$ 1,000 est. / 11/21/01 Daughter in law Beatrice And	drade
called cellar is dry they will hold off for now. Will call if leak continues.	

METER HISTORY								CHARGE OUTS	
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST	REMARKS	Barrier Barrier
					4				
-27-43		3,	/& mpire A x	1827366					-
1									