| (TOWN OF FREETOWY) APPLICATION No. 22136 8" C. I. | TAP CLEARED | | | |
|---|-------------|--------|--------|-------------|
| LOCATION: Braley Rd. Tn. of Freetown | DATE | BEF. | AFT. | REMARKS |
| OWNER: Town of Daptmouth | | | | |
| MEASURES: 8" C.I. 11-19-45 | | | | |
| 1-8" Darl. Tap. gate valve; 3-Cald. C.I. Gate Boxes | | | | |
| W from E bound stone 36.7 ft. | | | | |
| S from W Bound Stone 49.7 ft. E from Hydrant 68.8 ft. | | | | |
| Per memo dated Oct. 23, 1998 from Town of Freetown Water Commission | | | | |
| informed the Town of Freetown Water Commission has abandon the w | ater lin | e loca | ted on | Braley Rd., |
| Ea. Free. Acct # 22136A as of Oct. 9, 1998 | | | | |
| | | | | |
| TNACTIVE SER | | | | |
| TINAC IIIC SEX | | | | |
| | | | | |
| | * | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| METE | RH | ISTO | DRY | | | | | | | CHARGE OUTS | |
|------|-----|------|------|--------|----------|---------|---|--------------|---|-------------|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | IG TEST | | TEST REMARKS | | REMARKS | |
| DATE | OUT | SIZE | MAKE | HOMBER | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | - | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| /== | | | | | | | | | | | |
| | | | | | 1.4 | | | - | | | |
| | | 1 | 2.7 | | | | | | | | |
| | | | | | The same | - | | - | | | |
| | - | | | | 100 | 1 | | - | | | |
| | | | | | | - | | | + | | |