| APPLICATION No.: 22964 | | TAP CLEARED | | | | | | |
|--|--------------------|-------------|------|---------------|--|--|--|--|
| LOCATION: S.S. 1156 Sassaguin Ave., W x Tobey St. | DATE | BEF. | AFT. | REMARKS | | | | |
| OWNER: Blanche Lambert | 12/14/01 | 11:30 | am | 2001-500-6444 | | | | |
| MEASURES: 3/4" Copper 10-19-49 138 W from W line Tobey 141.4 ft. N from S line Sassaquin Ave. 4.1 ft. E from W line Meter Box 0.2 ft. | | 1 | | | | | | |
| April 24, 1975 Repaired service by installing a new 3 tap and a Smith Blair Saddle. 1 - 3/4" Corporation Hays 8" x 3/4" Smith Blair Saddle This service broken by Fantoni Const. | /L ₁ ** | | | | | | | |
| THAN FRZA SER. PIT 2-7-1995 | | | | | | | | |
| 2-7-1993 . 5042A | | | | <u> </u> | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | L. XI | | | | | | |

| METER HISTORY DATE SET OUT SIZE MAKE NUMBER READING TEST REMARKS | | | | | | | | | | CHARGE OUTS |
|---|-----|------|-------------|---------|---------|------|-----|---------|--|-------------|
| DATE | SET | SIZE | MAKE | NUMBER | READING | TEST | | REMARKS | | |
| | OUT | | | | | 1 | - 1 | | | 1. |
| | | | | | | | | | | · · |
| 10-28-49 | | 3/4 | Empire T 12 | 8579101 | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | - | | | | | - | | | |
| | | | | | | | | | | |
| - | | | | | | | | | | 4 |
| | , 1 | | | | | | | | | |
| | | - | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | - | | | | | | | | |
| | | | | | | | | | | |
| | - | | | | | | | | | |
| | | | | | | | | | | |
| | - | - | | | | | | | | |
| | | | | | | | | | | |
| | + | | | | 7 | | | | | |
| | | | | | | | | | | |

| the second second | APPLICATION No.: 32608 | 1 | TAP CLEARED | | | | | |
|-------------------|--|------|-------------|------|---------|--|--|--|
| LOCATION: 1 | 156 Cardinal Street | DATE | BEF. | AFT. | REMARKS | | | |
| | Annie Costa | | | | | | | |
| 31-313 MEASURES: | | 1 | | | | | | |
| P138 L377 | | | | | | | | |
| L 3 7 M | W 1.5', then 8' N from NW cor of pit Main to box 9.5 ft. | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | - | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | 1 | | | | | | |
| | | | | 1100 | | | | |
| , | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| METE | RH | IIST | ORY | | | | | | |
|------|-----|------|------|---------------|---------|-------|-----------|---------|----|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | REMARKS | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | - 3 | | | | 44.77 | un rectur | | 24 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | , | | | | | | | | |
| | | | | | | | | | |
| | , | | | Marie Parkers | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 9 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | 4 | | | | | | | | |
| | | | | | | | 4 | | |
| | | | | | | | | | |
| | | | | | | | \$ | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | 10 | | |
| | | | | | | | | | |

CHARGE OUTS