

APPLICATION No.: 23633

TAP CLEARED

LOCATION: E. S. # 60 West St., S x Elizabeth

OWNER: St. Lukes Hospital

MEASURES: 3" 7 TURNS Copper 10/11/51

1-3 Dar. Gate valve

S from S Elizabeth 44.6 ft.

~~W from E West 20.1 ft.~~

S from S Bldg. 3.2 ft.

E x W West S t. 20.5 ft.

Replaced old 3" C.I. Ser. #14688

May 22, 23, 1985 Repaired 3" gate for S t. Lukes
Hospital Boiler Room.

Replaced bonnet, spindle, wedges. Took a 3"
Darling gate apart (new one) and used parts to
repair gate.

This gate was broken while cement lining.

1 - #10 Caldwell Gate Box, complete

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS