

28

APPLICATION No.: 24162

TAP CLEARED

LOCATION: 309-13 Dartmouth St.OWNER: Edward J. Goulart ET Ux

MEASURES: 2" Copper Oct. 5, 1953

~~1-2" Dar. Tap Gate Valve; 1-1" C.I. Gatebox 220#~~

W from W line Dartmouth St. 22.6 ft.

N from S line Edwards St. ~~12-3-#~~ 12.6 ft.

Sept. 6, 1994 The 2" Darling Tapping gate valve broken. Removed gate valve & broken stem - replaced top section back. Installed at a point 6" south of old tapping gate: 2" curb stop w/ #10 gate box, compl.

1.5 ft. - 2" Copper tubing

1 - 2" x 2" cop to cop cplg., compression

6 - 2½" x ½" bolts & nuts for old gate

Note: This gate broken when flushing crew mistook it for a line gate - overturning gate valve. N/C to owner of laundromat.

/ INACTIVE SERVICE

[illegible]

CHARGE OUTS

[illegible]